Inspection Report

Mr. Home Owner

Property Address:

1000 Glenwick Dr Windermere FL 34786



1000 Glenwick Dr

Home Inspections by PJM Inc.

Bill Stewart HI9954 Subcontractor for Home Inspections by PJM, Inc

Table of Contents

Cover Page	1
Table of Contents	
Intro Page	
1 Roofing	
2 Exterior	
3 Garage	
4 Interiors	
5 Structural Components	
6 Plumbing System	
7 Electrical System	
8 Heating / Central Air Conditioning	
9 Insulation and Ventilation	
10 Built-In Kitchen Appliances	
11 Lawn Sprinklers	
12 Swimming Pools, Equipment and Safety	
General Summary	

1000 Glenwick Dr Page 2 of 87

Date: 8/7/2018	Time: 10:00 AM	Report ID:
Property: 1000 Glenwick Dr Windermere FL 34786	Customer: Mr. Home Owner	Real Estate Professional:

Comment Key or Definitions

The following definitions of comment descriptions represent this inspection report. All comments by the inspector should be considered before purchasing this home. Any recommendations by the inspector to repair or replace suggests a second opinion or further inspection by a qualified contractor. All costs associated with further inspection fees and repair or replacement of item, component or unit should be considered before you purchase the property.

<u>Inspected (IN)</u> = I visually observed the item, component or unit and if no other comments were made then it appeared to be functioning as intended allowing for normal wear and tear.

Not Inspected (NI)= I did not inspect this item, component or unit and made no representations of whether or not it was functioning as intended and will state a reason for not inspecting.

Not Present (NP) = This item, component or unit is not in this home or building.

Repair or Replace (RR) = The item, component or unit is not functioning as intended, or needs further inspection by a qualified contractor. Items, components or units that can be repaired to satisfactory condition may not need replacement.

Standards of Practice: In Attendance: Type of building: **INACHI National Association of Certified** Single Family (2 story) Customer and their agent Home Inspectors Approximate age of building: Temperature: Weather: Clear. Hot and Humid 14 years Over 65 (F) = 18 (C)Ground/Soil surface condition: Rain in last 3 days: Dry No

1000 Glenwick Dr Page 3 of 87

1. Roofing

The home inspector shall observe: Roof covering; Roof drainage systems; Flashings; Skylights, chimneys, and roof penetrations; and Signs of leaks or abnormal condensation on building components. The home inspector shall: Describe the type of roof covering materials; and Report the methods used to observe the roofing. The home inspector is not required to: Walk on the roofing; or Observe attached accessories including but not limited to solar systems, antennae, and lightning arrestors.

		IN	NI	NP	RR	Styles & Materials
1.0	Roof Coverings	•				Roof Covering: Ceramic/Clay
1.1	Flashings	•				Tile Viewed roof covering
1.2	Skylights, Chimneys and Roof Penetrations	•				from: Ground
1.3	Roof Drainage Systems	•				Binoculars Sky Light(s):
IN=	Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace	IN	NI	NP	RR	None
						Chimney (exterior):

Comments:

1.0 Functional at time of inspection.

Age 14 years Life expectancy based on 50 + years for tile roof systems is 36+ years left.



1.0 Item 1(Picture) Roof View



1.0 Item 2(Picture) Roof View

- **1.1** Functional at time of inspection.
- **1.2** Functional at time of inspection.
- **1.3** Functional at time of inspection.

The roof of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Roof coverings and skylights can appear to be leak proof during inspection and weather conditions. Our inspection makes an attempt to find a leak but sometimes cannot. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

1000 Glenwick Dr Page 4 of 87

2. Exterior



The home inspector shall observe: Wall cladding, flashings, and trim; Entryway doors and a representative number of windows; Garage door operators; Decks, balconies, stoops, steps, areaways, porches and applicable railings; Eaves, soffits, and fascias; and Vegetation, grading, drainage, driveways, patios, walkways, and retaining walls with respect to their effect on the condition of the building. The home inspector shall: Describe wall cladding materials; Operate all entryway doors and a representative number of windows; Operate garage door smanually or by using permanently installed controls for any garage door operator; Report whether or not any garage door operator will automatically reverse or stop when meeting reasonable resistance during closing; and Probe exterior wood components where deterioration is suspected. The home inspector is not required to observe: Storm windows, storm doors, screening, shutters, awnings, and similar seasonal accessories; Fences; Presence of safety glazing in doors and windows; Garage door operator remote control transmitters; Geological conditions; Soil conditions; Recreational facilities (including spas, saunas, steam baths, swimming pools, tennis courts, playground equipment, and other exercise, entertainment, or athletic facilities); Detached buildings or structures; or Presence or condition of buried fuel storage tanks. The home inspector is not required to: Move personal items, panels, furniture, equipment, plant life, soil, snow, ice or debris that obstructs access or visibility.



West Side



West Side Garage

1000 Glenwick Dr Page 5 of 87



North Side

1000 Glenwick Dr Page 6 of 87






East Side

North Side



Looking South

1000 Glenwick Dr Page 7 of 87





Rear Patio Area

Pool Screen Door North Side





East Side East Side

1000 Glenwick Dr Page 8 of 87





Rear Lanai Area

Pool Deck







Master Bedroom Patio Slider

1000 Glenwick Dr Page 9 of 87





South Side

Main Entry Doors







Driveway

1000 Glenwick Dr Page 10 of 87

		IN	NI	NP	RR	Styles & Materials
2.0	Wall Cladding Flashing and Trim	•				Siding Style: Cement stucco
2.1	Doors (Exterior)	•			•	Siding Material: Masonry
2.2	Windows	•				Exterior Entry Doors: Fiberglass
2.3	Decks, Balconies, Stoops, Steps, Areaways, Porches, Patio/Cover and Applicable Railings	•				Single pane Appurtenance:
2.4	Vegetation, Grading, Drainage, Driveways, Patio Floor, Walkways and Retaining Walls (With respect to their effect on the condition of the building)	•				Covered porch Sidewalk Patio
2.5	Eaves, Soffits and Fascias	•			•	Driveway: Brick Pavers
IN=	Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace	IN	NI	NP	RR	DIICK FAVEIS

Comments:

2.0 Functional at time of inspection.

2.1 (1) Wood rot fungi present at the pool bath exterior door frame. Recommend repair by a qualified person.







Page 11 of 87 1000 Glenwick Dr

(2) Wood rot fungi present at the master bedroom exterior door frame. Recommend repair by a qualified person.






2.1 Item 3(Picture) Master Bedroom Exterior Door

2.1 Item 4(Picture) Master Bedroom Exterior Door

- **2.2** Functional at time of inspection.
- 2.3 Functional at time of inspection.
- 2.4 Functional at time of inspection.

2.5 Visible wood rot fungi or water damage at the fascia board located in areas. Recommend repair by a qualified person.







2.5 Item 2(Picture) North Side

1000 Glenwick Dr Page 12 of 87



2.5 Item 3(Picture) South Side



2.5 Item 4(Picture) South Side



2.5 Item 5(Picture) South Side



2.5 Item 6(Picture) West Side

1000 Glenwick Dr Page 13 of 87

Owner

The exterior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.


1000 Glenwick Dr Page 14 of 87


3. Garage


		IN	NI	NP	RR	Styles & Materials
3.0	Garage Ceilings	•			•	Garage Door Type: One automatic
3.1	Garage Walls (including Firewall Separation)	•				Two automatic Garage Door Material:
3.2	Garage Floor	•				Metal Auto-opener
3.3	Garage Door (s)	•				Manufacturer: GENIE
3.4	Occupant Door (from garage to inside of home)	•				OLIVIL
3.5	Garage Door Operators (Report whether or not doors will reverse when met with resistance)	•			•	
IN=	Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace	IN	NI	NP	RR	

Comments:

3.0 Visible water damage at the garage ceiling tested with moisture meter currently dry. Recommend further evaluation and repair if needed by a licensed roofing contractor.








3.0 Item 2(Picture) Attic Side Of Garage Ceiling

1000 Glenwick Dr Page 15 of 87




3.0 Item 3(Picture) Attic View Above Garage .

3.1 Functional at time of inspection.







3.1 Item 2(Picture) East Wall

1000 Glenwick Dr Page 16 of 87



3.1 Item 3(Picture) South Wall

- **3.2** Functional at time of inspection.
- **3.3** Functional at time of inspection.




3.3 Item 1(Picture) Two Car Garage Door



3.3 Item 2(Picture) Single Car Garage Door

1000 Glenwick Dr Page 17 of 87





3.3 Item 4(Picture) Two Car Garage Door Interior

3.3 Item 3(Picture) Single Car Garage Door Interior

1000 Glenwick Dr Page 18 of 87

3.4 Functional at time of inspection.



3.4 Item 1(Picture) Occupant Door

1000 Glenwick Dr Page 19 of 87

3.5 (1) Single car garage door operator would operate but not open door at time of inspection. Recommend repair by a qualified person.



3.5 Item 1(Picture) Single Car Garage Door Operator

1000 Glenwick Dr Page 20 of 87

(2) Two car garage door operator was functional but would not reverse when tested. Recommend repair by a qualified person.



3.5 Item 2(Picture) Two Car Garage Door Operator

1000 Glenwick Dr Page 21 of 87

4. Interiors

The home inspector shall observe: Walls, ceiling, and floors; Steps, stairways, balconies, and railings; Counters and a representative number of installed cabinets; and A representative number of doors and windows. The home inspector shall: Operate a representative number of windows and interior doors; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector is not required to observe: Paint, wallpaper, and other finish treatments on the interior walls, ceilings, and floors; Carpeting; or Draperies, blinds, or other window treatments.






Bonus Room

Upstairs Bath


1000 Glenwick Dr Page 22 of 87





Upstairs Hall






Bonus Room




1000 Glenwick Dr Page 23 of 87



Bedroom #1 Living Space

Bedroom #1 Living Space







Bedroom #1

1000 Glenwick Dr Page 24 of 87





Bath #1

Bath #1





Bath #1 Bath #1


1000 Glenwick Dr Page 25 of 87



Family Room



Kitchen Nook









1000 Glenwick Dr Page 26 of 87





Kitchen

Living Room








Foyer Hall

Page 27 of 87 1000 Glenwick Dr





Bedroom #2

Bedroom #3








Hall Bath

1000 Glenwick Dr Page 28 of 87





Master Bath Master Bath





Master Bath Master Bath


1000 Glenwick Dr Page 29 of 87





Master Bath

Master Closet









Master Bedroom

1000 Glenwick Dr Page 30 of 87







Master Bedroom



Master Bedroom



Master Bedroom

IN NI NP RR

4.0	Ceilings	•		
4.1	Walls	•		
4.2	Floors	•		•
4.3	Steps, Stairways, Balconies and Railings	•		
4.4	Counters and Cabinets (representative number)	•		•

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

IN NI NP RR Styles & Materials

Ceiling Materials:
Gypsum Board

Wall Material:

Gypsum Board Tile

Floor Covering(s):
Carpet
Tile

Interior Doors:

Hollow core Masonite

1000 Glenwick Dr Page 31 of 87

		IN	NI	NP	RR	Raised panel
						Window Types:
4.5	Doors (representative number)	•				Single-hung Single pane
4.6	Windows (representative number)	•				Glass Block Window Manufacturer:
IN=	Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace	IN	NI	NP	RR	UNKNOWN
						Cabinetry: Wood Laminate
						Countertop: Laminate Cultured marble Granite

Comments:

- **4.0** Functional at time of inspection.
- **4.1** Functional at time of inspection.
- 4.2 Carpet seam located in bonus room was not functional at time of inspection. Recommend repair by a qualified person.



4.2 Item 1(Picture) Bonus Room

1000 Glenwick Dr Page 32 of 87

- **4.3** Functional at time of inspection.
- **4.4** (1) Cabinets and counter top located in mud room are not installed as permanent. The counter top is laying on the cabinets. Recommend repair by a qualified person.





4.4 Item 1(Picture) Mud Room

4.4 Item 2(Picture) Mud Room Counter Top

(2) Laundry room counter was cut and not finished this is for your information.



4.4 Item 3(Picture) Laundry Room

1000 Glenwick Dr Page 33 of 87

- **4.5** Functional at time of inspection.
- **4.6** Functional at time of inspection.

The interior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection did not involve moving furniture and inspecting behind furniture, area rugs or areas obstructed from view. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

1000 Glenwick Dr Page 34 of 87

5. Structural Components

The Home Inspector shall observe structural components including foundations, floors, walls, columns or piers, ceilings and roof. The home inspector shall describe the type of Foundation, floor structure, wall structure, columns or piers, ceiling structure, roof structure. The home inspector shall: Probe structural components where deterioration is suspected; Enter under floor crawl spaces, basements, and attic spaces except when access is obstructed, when entry could damage the property, or when dangerous or adverse situations are suspected; Report the methods used to observe under floor crawl spaces and attics; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector is not required to: Enter any area or perform any procedure that may damage the property or its components or be dangerous to or adversely effect the health of the home inspector or other persons.

	Favordations Basement and Convolunces (Basement sinus of abroament or boundful water			
5.0	Foundations, Basement and Crawlspace (Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components.)	•		
5.1	Walls (Structural)	•		
5.2	Columns or Piers	•		
5.3	Floors (Structural)	•		
5.4	Ceilings (Structural)	•		
5.5	Roof Structure and Attic	•		•

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

IN NI NP RR Styles & Materials

Foundation:

Poured concrete

Floor Structure:

Slab

Wall Structure:

Masonry

Columns or Piers:

Masonry block

Ceiling Structure:

4" or better

Roof Structure:

Engineered wood trusses Lateral bracing

Plywood

Roof-Type:

Hip

IN NI NP RR

Method used to observe

attic:

Walked

Attic info:


Attic access Scuttle hole Light in attic

Comments:

1000 Glenwick Dr Page 35 of 87

5.5 Rodent droppings present attic access at the second floor access. Rat traps in the attic and dead rat was visible in rat trap. Recommend further evaluation by a critter control company.







5.5 Item 2(Picture) Rodent Droppings

1000 Glenwick Dr Page 36 of 87



5.5 Item 3(Picture) Dead Rat

The structure of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

1000 Glenwick Dr Page 37 of 87

6. Plumbing System

The home inspector shall observe: Interior water supply and distribution system, including: piping materials, supports, and insulation; fixtures and faucets; functional flow; leaks; and cross connections; Interior drain, waste, and vent system, including: traps; drain, waste, and vent piping; piping supports and pipe insulation; leaks; and functional drainage; Hot water systems including: water heating equipment; normal operating controls; automatic safety controls; and chimneys, flues, and vents; Fuel storage and distribution systems including: interior fuel storage equipment, supply piping, venting, and supports; leaks; and Sump pumps. The home inspector shall describe: Water supply and distribution piping materials; Drain, waste, and vent piping materials; Water heating equipment; and Location of main water supply shutoff device. The home inspector shall operate all plumbing fixtures, including their faucets and all exterior faucets attached to the house, except where the flow end of the faucet is connected to an appliance. The home inspector is not required to: State the effectiveness of anti-siphon devices; Determine whether water supply and waste disposal systems are public or private; Operate automatic safety controls; Operate any valve except water closet flush valves, fixture faucets, and hose faucets; Observe: Water conditioning systems; Fire and lawn sprinkler systems; On-site water supply quantity and quality; On-site waste disposal systems; Foundation irrigation systems; Spas, except as to functional flow and functional drainage; Swimming pools; Solar water heating equipment; or Observe the system for proper sizing, design, or use of proper materials.



Water Pressure #89 PSI



Washer Water Supply & Drain

1000 Glenwick Dr Page 38 of 87



Spa Tub

		IN	NI	NP	RR
6.0	Plumbing Drain, Waste and Vent Systems	•			
6.1	Plumbing Water Supply, Distribution System and Fixtures	•			•
6.2	Hot Water Systems, Controls, Chimneys, Flues and Vents	•			
6.3	Main Water Shut-off Device (Describe location)	•			
6.4	Fuel Storage and Distribution Systems (Interior fuel storage, piping, venting, supports, leaks)	•			
6.5	Main Fuel Shut-off (Describe Location)	•			
6.6	Sump Pump			•	

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

Styles & Materials

Water Source:
Public

Water Filters:

None

Plumbing Water Supply

(into home):

PVC

Plumbing Water

Distribution (inside home):

CPVC

Washer Drain Size:

2" Diameter

Plumbing Waste:

PVC

IN NI NP RR

Water Heater Power

Source:

Gas (quick recovery)

Water Heater Capacity:

50 Gallon (2-3 people)

Manufacturer:

RHEEM

Water Heater Location:

Utility Room

Comments:

1000 Glenwick Dr Page 39 of 87

- **6.0** Functional at time of inspection.
- **6.1** (1) Water leaking at the handle when turned on at the hose bib located on the South Side of home. Recommend repair by a qualified person.



6.1 Item 1(Picture) South Side

1000 Glenwick Dr Page 40 of 87


(2) Kitchen sink faucet is loose. Recommend repair by a qualified person.



6.1 Item 2(Picture) Kitchen Sink Faucet

1000 Glenwick Dr Page 41 of 87

(3) Control rod that operates the sink stopper #1 in master bath was not functional at time of inspection. Recommend repair by a qualified person.




6.1 Item 3(Picture)

1000 Glenwick Dr Page 42 of 87

6.2 Functional at time of inspection.

Age 14 years Life expectancy based on a 20 year life cycle is 6 years left.







6.2 Item 2(Picture) Gas Water Heater

1000 Glenwick Dr Page 43 of 87



6.2 Item 3(Picture) WH Burner



6.2 Item 4(Picture) Hot Water Heater Label

1000 Glenwick Dr Page 44 of 87

6.3 Main water shut off valve located on the South side of homes exterior.



6.3 Item 1(Picture) South Side

1000 Glenwick Dr Page 45 of 87

- **6.4** Functional at time of inspection.
- **6.5** Main fuel shut off located outside on the North exterior wall at the gas meter.



6.5 Item 1(Picture) North Side

The plumbing in the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Washing machine drain line for example cannot be checked for leaks or the ability to handle the volume during drain cycle. Older homes with galvanized supply lines or cast iron drain lines can be obstructed and barely working during an inspection but then fails under heavy use. If the water is turned off or not used for periods of time (like a vacant home waiting for closing) rust or deposits within the pipes can further clog the piping system. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

1000 Glenwick Dr Page 46 of 87

7. Electrical System

The home inspector shall observe: Service entrance conductors; Service equipment, grounding equipment, main over current device, and main and distribution panels; Amperage and voltage ratings of the service; Branch circuit conductors, their over current devices, and the compatibility of their ampacities and voltages; The operation of a representative number of installed ceiling fans, lighting fixtures, switches and receptacles located inside the house, garage, and on the dwelling's exterior walls; The polarity and grounding of all receptacles within six feet of interior plumbing fixtures, and all receptacles in the garage or carport, and on the exterior of inspected structures; The operation of ground fault circuit interrupters; and Smoke detectors. The home inspector shall describe: Service amperage and voltage; Service entry conductor materials; Service type as being overhead or underground; and Location of main and distribution panels. The home inspector shall report any observed aluminum branch circuit wiring. The home inspector shall report on presence or absence of smoke detectors, and operate their test function, if accessible, except when detectors are part of a central system. The home inspector is not required to: Insert any tool, probe, or testing device inside the panels; Test or operate any over current device except ground fault circuit interrupters; Dismantle any electrical device or control other than to remove the covers of the main and auxiliary distribution panels; or Observe: Low voltage systems; Security system devices, heat detectors, or carbon monoxide detectors; Telephone, security, cable TV, intercoms, or other ancillary wiring that is not a part of the primary electrical distribution system; or Built-in vacuum equipment.

		IN	NI	NP	RR	Styles & Materials
7.0	Service Entrance Conductors	•				Electrical Service Conductors:
7.1	Service and Grounding Equipment, Main Overcurrent Device, Main and Distribution Panels	•				Below ground Aluminum
7.2	Branch Circuit Conductors, Overcurrent Devices and Compatability of their Amperage and Voltage	•			•	Panel Capacity: (2) 150 AMP service panel
7.3	Connected Devices and Fixtures (Observed from a representative number operation of ceiling fans, lighting fixtures, switches and receptacles located inside the house, garage, and on the dwelling's exterior walls)	•				Panel Type: Circuit breakers Electric Panel
7.4	Polarity and Grounding of Receptacles within 6 feet of interior plumbing fixtures, all receptacles in garage, carport and exterior walls of inspected structure	•				Manufacturer: SQUARE D Branch wire 15 and 20
7.5	Operation of GFCI (Ground Fault Circuit Interrupters)	•			•	AMP:
7.6	Location of Main and Distribution Panels	•				Copper Wiring Methods:
7.7	Smoke Detectors	•				Romex
IN=	Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace	IN	NI	NP	RR	

Comments:

1000 Glenwick Dr Page 47 of 87

7.0 Functional at time of inspection.







7.0 Item 2(Picture) Panel B

1000 Glenwick Dr Page 48 of 87

7.1 Functional at time of inspection.







7.1 Item 2(Picture) 150 Amp Main Circuit Breaker


1000 Glenwick Dr Page 49 of 87



7.1 Item 3(Picture) Main Panel Ground Wire

1000 Glenwick Dr Page 50 of 87

7.2 Arc breaker 12,14,16,18 located in the electrical sub panel A would not trip when tested. Recommend replace by a licensed electrician.



7.2 Item 1(Picture) Garage Electrical Sub Panel

1000 Glenwick Dr Page 51 of 87

- **7.3** Functional at time of inspection.
- **7.4** Functional at time of inspection.
- **7.5** GFCi located on the North side of home by the irrigation controller was not functional at time of inspection. Recommend replace by a qualified person.



7.5 Item 1(Picture) North Side Exterior

1000 Glenwick Dr Page 52 of 87

7.6 (1) Main electrical panels A & B is located on the North exterior wall of the home.








7.6 Item 2(Picture) Main Electrical Panel A With Cover Removed

1000 Glenwick Dr Page 53 of 87








7.6 Item 4(Picture) Main Electrical Panel B With Cover Removed

1000 Glenwick Dr Page 54 of 87

(2) Sub electrical panel A & B are located in the garage.








7.6 Item 6(Picture) Sub Electrical Panel A With Cover Removed

1000 Glenwick Dr Page 55 of 87







7.6 Item 8(Picture) Sub Electrical Panel B With Cover Removed

7.7 Functional at time of inspection.

The electrical system of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Outlets were not removed and the inspection was only visual. Any outlet not accessible (behind the refrigerator for example) was not inspected or accessible. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

1000 Glenwick Dr Page 56 of 87

8. Heating / Central Air Conditioning

The home inspector shall observe permanently installed heating and cooling systems including: Heating equipment; Cooling Equipment that is central to home; Normal operating controls; Automatic safety controls; Chimneys, flues, and vents, where readily visible; Solid fuel heating devices; Heat distribution systems including fans, pumps, ducts and piping, with supports, insulation, air filters, registers, radiators, fan coil units, convectors; and the presence of an installed heat source in each room. The home inspector shall describe: Energy source; and Heating equipment and distribution type. The home inspector shall operate the systems using normal operating controls. The home inspector shall open readily openable access panels provided by the manufacturer or installer for routine homeowner maintenance. The home inspector is not required to: Operate heating systems when weather conditions or other circumstances may cause equipment damage; Operate automatic safety controls; Ignite or extinguish solid fuel fires; or Observe: The interior of flues; Fireplace insert flue connections; Humidifiers; Electronic air filters; or The uniformity or adequacy of heat supply to the various rooms.

8.0	Heating Equipment	•		
8.1	Normal Operating Controls	•		
8.2	Automatic Safety Controls	•		
8.3	Distribution Systems (including fans, pumps, ducts and piping, with supports, insulation, air filters, registers, radiators, fan coil units and convectors)	•		
8.4	Presence of Installed Heat Source in Each Room	•		
8.5	Chimneys, Flues and Vents (for fireplaces, gas water heaters or heat systems)	•		
8.6	Solid Fuel Heating Devices (Fireplaces, Woodstove)		•	
8.7	Gas/LP Firelogs and Fireplaces		•	
8.8	Cooling and Air Handler Equipment	•		
8.9	Normal Operating Controls	•		
8.10	Presence of Installed Cooling Source in Each Room	•		

IN NI NP RR IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

IN NI NP RR Styles & Materials

Heat Type:

Heat Pump Forced Air (also provides cool air) Forced Air Electric heat

Energy Source:

Electric

Number of Heat Systems

(excluding wood):

Heat System Brand:

GOODMAN LENNOX

Ductwork:

Insulated

Filter Type:

Disposable

Filter Size:

14x14 30 x 18 x 1

Cooling Equipment Type:

Heat Pump Forced Air (also provides warm air)

Cooling Equipment Energy

Source:

Electricity

Central Air Manufacturer:

GOODMAN LENNOX

Number of AC Only Units:

Two

Comments:

1000 Glenwick Dr Page 57 of 87

- **8.0** Functional at time of inspection.
- **8.1** Functional at time of inspection.
- **8.2** Functional at time of inspection.
- **8.3** Functional at time of inspection.



8.3 Item 1(Picture) System #1 Filter Location



8.3 Item 2(Picture) Filter Dirty Needs Changed System #1

1000 Glenwick Dr Page 58 of 87



8.3 Item 3(Picture) System #2 Filter Location

1000 Glenwick Dr Page 59 of 87

- **8.4** Functional at time of inspection.
- **8.5** Item 1(Picture) Functional at time of inspection.



8.5 Item 1(Picture) WH Flue

1000 Glenwick Dr Page 60 of 87

8.8 (1) Functional at time of inspection.

System #1 Main House

Lennox / Goodman - 12 Seer 5 - Ton Electric Heat Pump System

Indoor Air Handler - Age -14 years Old Life expectancy based on a 15 year life cycle is 1 + years left

Outdoor Heat Pump - Age 7 Years Old Life expectancy based on a 15 year life cycle is 8 years left.

System #2 Bonus Room

Lennox - 12 seer 2 - Ton Electric heat Pump System.

Age 14 Years Life expectancy based on a 15 year life cycle is 1 + years left



8.8 Item 1(Picture) Outdoor Heat Pump System #1



8.8 Item 2(Picture) Outdoor Heat Pump System #1 Label

1000 Glenwick Dr Page 61 of 87



SIN 580AJ22799

CONTAINS HCFC - 22 DESIGN PRESS


FACTORY CHARGE HI 278 PSIGN
FACTORY C

8.8 Item 3(Picture)

8.8 Item 4(Picture)




8.8 Item 5(Picture)



8.8 Item 6(Picture)

1000 Glenwick Dr Page 62 of 87





8.8 Item 7(Picture)

8.8 Item 8(Picture)

1000 Glenwick Dr Page 63 of 87

(2) The ambient air test was performed by using thermometers on the air handler of Heat pump in cool mode to determine if the difference in temperatures of the supply and return air are between 14 degrees and 22 degrees which indicates that the unit is cooling as intended. The supply air temperature on your system read 52 degrees, and the return air temperature was 71 degrees. This indicates the range in temperature drop is normal.





8.8 Item 9(Picture) Supply Air Cooling Temp

8.8 Item 10(Picture) Return Air Cooling Temp

- **8.9** Functional at time of inspection.
- **8.10** Functional at time of inspection.

The heating and cooling system of this home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection is not meant to be technically exhaustive. The inspection does not involve removal and inspection behind service door or dismantling that would otherwise reveal something only a licensed heat contractor would discover. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

1000 Glenwick Dr Page 64 of 87

9. Insulation and Ventilation

The home inspector shall observe: Insulation and vapor retarders in unfinished spaces; Ventilation of attics and foundation areas; Kitchen, bathroom, and laundry venting systems; and the operation of any readily accessible attic ventilation fan, and, when temperature permits, the operation of any readily accessible thermostatic control. The home inspector shall describe: Insulation in unfinished spaces; and Absence of insulation in unfinished space at conditioned surfaces. The home inspector shall: Move insulation where readily visible evidence indicates the need to do so; and Move insulation where chimneys penetrate roofs, where plumbing drain/waste pipes penetrate floors, adjacent to earth filled stoops or porches, and at exterior doors. The home inspector is not required to report on: Concealed insulation and vapor retarders; or Venting equipment that is integral with household appliances.



Dryer Vent

9.0 Insulation in Attic 9.1 Ventilation of Attic and Foundation Areas 9.2 Venting Systems (Kitchens, Baths and Laundry) IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace IN NI NP RR

Styles & Materials

Attic Insulation:

Blown Batt Fiberglass Cellulose R-19 or better

Ventilation:

Ridge vents Soffit Vents

Exhaust Fans:

Fan only

Dryer Power Source:

220 Electric

Dryer Vent:

Both Flexible Metal Metal

Comments:

1000 Glenwick Dr Page 65 of 87

Owner

- 9.0 Functional at time of inspection.
- **9.1** Functional at time of inspection.
- 9.2 Functional at time of inspection.

The insulation and ventilation of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Venting of exhaust fans or clothes dryer cannot be fully inspected and bends or obstructions can occur without being accessible or visible (behind wall and ceiling coverings). Only insulation that is visible was inspected. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

1000 Glenwick Dr Page 66 of 87

10. Built-In Kitchen Appliances

The home inspector shall observe and operate the basic functions of the following kitchen appliances: Permanently installed dishwasher, through its normal cycle; Range, cook top, and permanently installed oven; Trash compactor; Garbage disposal; Ventilation equipment or range hood; and Permanently installed microwave oven. The home inspector is not required to observe: Clocks, timers, self-cleaning oven function, or thermostats for calibration or automatic operation; Non built-in appliances; or Refrigeration units. The home inspector is not required to operate: Appliances in use; or Any appliance that is shut down or otherwise inoperable.

			 	1111	•
10.0	Dishwasher	•			Dishwashe KITCHENA
10.1	Ranges/Ovens/Cooktops	•			Disposer B BADGER
10.2	Range Hood (s)		•		Range/Ove KITCHEN
10.3	Trash Compactor		•		Built in Mic
10.4	Food Waste Disposer	•			KITCHEN
10.5	Microwave Cooking Equipment	•			Refrigerato KITCHEN
10.6	Refrigerator	•			Washer: Samsung
10.7	Washer	•			Electric Dry Samsung
10.8	Dryer	•			g

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

IN NI NP RR

IN NI NP RR Styles & Materials

er Brand: AID

Brand:

en:

N AIDE

crowave: L ELECTRIC N AIDE

or:


NAIDE

ryer:


Comments:

1000 Glenwick Dr Page 67 of 87

10.0 Functional at time of inspection.







10.0 Item 2(Picture) DW Interior

1000 Glenwick Dr Page 68 of 87

10.1 Functional at time of inspection.

Ovens tested at 350 degrees



10.1 Item 1(Picture) Gas Cook Top



10.1 Item 2(Picture) Double Oven

1000 Glenwick Dr Page 69 of 87





10.1 Item 3(Picture) Upper Oven Temp

10.1 Item 4(Picture) Lower Oven Temp

1000 Glenwick Dr Page 70 of 87

10.4 Functional at time of inspection.



10.4 Item 1(Picture) Food Waste Disposer

10.5 Functional at time of inspection.



10.5 Item 1(Picture) Kitchen Microwave



10.5 Item 2(Picture) Microwave Interior

1000 Glenwick Dr Page 71 of 87



10.5 Item 3(Picture) Second Microwave

10.6 Functional at time of inspection.



10.6 Item 1(Picture) Refrigerator

10.7 Functional at time of inspection.

10.8 Functional at time of inspection.

The built-in appliances of the home were inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

1000 Glenwick Dr Page 72 of 87

11. Lawn Sprinklers

		IN	NI	NP	RR
11.0	Sprinkler Operation	•			
11.1	Controllers	•			
11.2	Rotary Heads	•			
11.3	Visible Connections or Clamps	•			
11.4	Drains	•			
11.5	Sensors	•			

IN= Inspected, NI= Not Inspected, NP= Not Present, RR= Repair or Replace

IN NI NP RR

Comments:

- **11.0** Functional at time of inspection.
- **11.1** Functional at time of inspection.



11.1 Item 1(Picture) Irrigation Controller North Side

1000 Glenwick Dr Page 73 of 87

- **11.2** Functional at time of inspection.
- 11.3 Functional at time of inspection.
- **11.4** Functional at time of inspection.
- **11.5** Functional at time of inspection.

1000 Glenwick Dr Page 74 of 87

12. Swimming Pools, Equipment and Safety

Pools are fun, but children and adults can lose their life quickly. Over 4000 lives annually are lost with one-third under the age of 14. *A child can drown in the time it takes to answer a phone*. A swimming pool is 14 times more likely than a motor vehicle to be involved in the death of a child age 4 and under. An estimated 5,000 children ages 14 and under are hospitalized due to near-drownings each year; 15 percent die in the hospital and as many as 20 percent suffer severe, permanent brain damage. Of all preschoolers who drown, 70 percent are in the care of one or both parents at the time of the drowning and 75 percent are missing from sight for five minutes or less. Drowning surpasses all other causes of death to children age 14 and under in Arizona, California, Florida, Hawaii, Montana, Nevada, Oregon, Utah and Washington.

A <u>pool alarm</u> with a loud speaker system to sound outside as well as inside the home could save a life. Even if you do not have children you should be concerned. 35% of children that drowned did so in someone else's pool. For more info, do an Internet search on pool safety or visit this website: http://www.ihf.org/foryourhealth/article_children.html





Pool Equipment

Pool Heater

1000 Glenwick Dr Page 75 of 87





Pool Filter

Pool Pump







Pool Timer

1000 Glenwick Dr Page 76 of 87





Hot Tub / Spa

Pool Chlorinator





Pool Water Feature Pool View

1000 Glenwick Dr Page 77 of 87





Spa With Jets Operating

Child Safety Fence

Styles & Materials

Style: In ground Heated

Shape: Rectangle

Wall Material: Gunite (concrete)

IN Yes NI NP RR No

12.0	Operational Condition of Pool	•			•	
12.1	Surface Walls and Floor of Pool	•				
12.2	Permanent Accessories Condition	•				
12.3	Pumps for Circulation of Water	•			•	
12.4	Pumps for Vacuum or Cleaning	•				
12.5	Pool Heaters	•			•	
12.6	Verify the Electrucal outlet (s) and any Lighting for Pools is on a Ground Fault Circuit (GFCI)	•				
12.7	Overflow Skimmers and Drains	•				
12.8	Do Steps and ladders exist on both sides of the pool?	•				
12.9	Are there any obstructions (walls, shrubs, etc.) that would prevent full view of pool from home?	•	•			
12.10	Is the pool fenced?	•	•			
12.11	Does the fence have a self closing latch and a lock on door?	•	•			
12.12	Can someone climb the fence by the use of personal items or structures against fence?	•				•
12.13	Does the door latch height and location attempt to make difficult for young children to reach?	•	•			
12.14	Are Electric Lights Secure?	•	•			
12.15	Water Level should be within inches from Rim to allow an easier climb out.	•	•			
12.16	Pool Design at waters edge should not include protrusions that could injure swimmer	•				
12.17	Does the surface around pool encourage drainage away from pool?	•	•			

IN= Inspected, Yes= Yes, NI= Not Inspected, NP= Not Present, RR= Repair or Replace, No= No

IN Yes NI NP RR No

Comments:

Page 78 of 87 1000 Glenwick Dr

12.0 Air bubbles present in the pool pump lid indicating a possible leak. Recommend further evaluation and repair by a pool service provider.








12.0 Item 2(Picture) Pool Service Company

1000 Glenwick Dr Page 79 of 87

- **12.1** Functional at time of inspection.
- **12.2** Functional at time of inspection.
- **12.3** Functional at time of inspection.
- **12.4** Functional at time of inspection.
- 12.5 (1) LCD Screen was not functional at time of inspection recommend further evaluation and repair by a pool service company.



12.5 Item 1(Picture) Pool Heater LCD Screen

1000 Glenwick Dr Page 80 of 87


(2) Electrical conduit that serves the pool heater is two short. Recommend repair by a qualified person.



12.5 Item 2(Picture) Pool Heater Electrical Conduit

1000 Glenwick Dr Page 81 of 87

12.6 Functional at time of inspection.




12.6 Item 1(Picture) Pool Light GFCI

- **12.7** Functional at time of inspection.
- 12.8 Functional at time of inspection.



12.8 Item 1(Picture) Swim Ledge

1000 Glenwick Dr Page 82 of 87



12.8 Item 2(Picture) Pool Steps

12.9 Raised Hot tub and planter obstructs the view of the pool.



12.9 Item 1(Picture) Pool View

1000 Glenwick Dr Page 83 of 87

- 12.10 Functional at time of inspection.
- **12.11** Functional at time of inspection.
- 12.12 Functional at time of inspection.
- **12.13** Functional at time of inspection.
- 12.14 Functional at time of inspection.
- 12.15 Functional at time of inspection.
- 12.16 Functional at time of inspection.
- **12.17** Functional at time of inspection.

Unless so mentioned in this report, I did not test water for bacteria or quality. The pool was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

1000 Glenwick Dr Page 84 of 87

General Summary

Home Inspections by PJM Inc.

Subcontractor for Home Inspections by PJM, Inc.

Customer

Mr. Home Owner

Address

1000 Glenwick Dr Windermere FL 34786

The following items or discoveries indicate that these systems or components **do not function as intended** or **adversely affects the habitability of the dwelling**; or **warrants further investigation by a specialist**, or **requires subsequent observation**. This summary shall not contain recommendations for routine upkeep of a system or component to keep it in proper functioning condition or recommendations to upgrade or enhance the function or efficiency of the home. This Summary is not the entire report. The complete report may include additional information of concern to the customer. It is recommended that the customer read the complete report.

2. Exterior



2.1 Doors (Exterior)

Inspected, Repair or Replace

- (1) Wood rot fungi present at the pool bath exterior door frame. Recommend repair by a qualified person.
- (2) Wood rot fungi present at the master bedroom exterior door frame. Recommend repair by a qualified person.
- 2.5 Eaves, Soffits and Fascias

Inspected, Repair or Replace

Visible wood rot fungi or water damage at the fascia board located in areas. Recommend repair by a qualified person.

3. Garage

3.0 Garage Ceilings

Inspected, Repair or Replace

Visible water damage at the garage ceiling tested with moisture meter currently dry. Recommend further evaluation and repair if needed by a licensed roofing contractor.

3.5 Garage Door Operators (Report whether or not doors will reverse when met with resistance)

Inspected, Repair or Replace

- (1) Single car garage door operator would operate but not open door at time of inspection. Recommend repair by a qualified person.
- (2) Two car garage door operator was functional but would not reverse when tested. Recommend repair by a qualified person.

1000 Glenwick Dr Page 85 of 87

4. Interiors

4.2 Floors

Inspected, Repair or Replace

Carpet seam located in bonus room was not functional at time of inspection. Recommend repair by a qualified person.

4.4 Counters and Cabinets (representative number)

Inspected, Repair or Replace

- (1) Cabinets and counter top located in mud room are not installed as permanent. The counter top is laying on the cabinets. Recommend repair by a qualified person.
- (2) Laundry room counter was cut and not finished this is for your information.

5. Structural Components

5.5 Roof Structure and Attic

Inspected, Repair or Replace

Rodent droppings present attic access at the second floor access. Rat traps in the attic and dead rat was visible in rat trap. Recommend further evaluation by a critter control company.

6. Plumbing System

6.1 Plumbing Water Supply, Distribution System and Fixtures

Inspected, Repair or Replace

- (1) Water leaking at the handle when turned on at the hose bib located on the South Side of home. Recommend repair by a qualified person.
- (2) Kitchen sink faucet is loose. Recommend repair by a qualified person.
- (3) Control rod that operates the sink stopper #1 in master bath was not functional at time of inspection. Recommend repair by a qualified person.

7. Electrical System

7.2 Branch Circuit Conductors, Overcurrent Devices and Compatability of their Amperage and Voltage

Inspected, Repair or Replace

Arc breaker 12,14,16,18 located in the electrical sub panel A would not trip when tested. Recommend replace by a licensed electrician.

7.5 Operation of GFCI (Ground Fault Circuit Interrupters)

Inspected, Repair or Replace

GFCi located on the North side of home by the irrigation controller was not functional at time of inspection. Recommend replace by a qualified person.

12. Swimming Pools, Equipment and Safety

12.5 Pool Heaters

Inspected, Repair or Replace

- (1) LCD Screen was not functional at time of inspection recommend further evaluation and repair by a pool service company.
- (2) Electrical conduit that serves the pool heater is two short. Recommend repair by a qualified person.

1000 Glenwick Dr Page 86 of 87

12.9 Are there any obstructions (walls, shrubs, etc.) that would prevent full view of pool from home? Inspected, Yes

Raised Hot tub and planter obstructs the view of the pool.

Home inspectors are not required to report on the following: Life expectancy of any component or system; The causes of the need for a repair; The methods, materials, and costs of corrections; The suitability of the property for any specialized use; Compliance or non-compliance with codes, ordinances, statutes, regulatory requirements or restrictions; The market value of the property or its marketability; The advisability or inadvisability of purchase of the property; Any component or system that was not observed; The presence or absence of pests such as wood damaging organisms, rodents, or insects; or Cosmetic items, underground items, or items not permanently installed. Home inspectors are not required to: Offer warranties or guarantees of any kind; Calculate the strength, adequacy, or efficiency of any system or component; Enter any area or perform any procedure that may damage the property or its components or be dangerous to the home inspector or other persons; Operate any system or component that is shut down or otherwise inoperable; Operate any system or component that does not respond to normal operating controls; Disturb insulation, move personal items, panels, furniture, equipment, plant life, soil, snow, ice, or debris that obstructs access or visibility; Determine the presence or absence of any suspected adverse environmental condition or hazardous substance, including but not limited to mold, toxins, carcinogens, noise, contaminants in the building or in soil, water, and air; Determine the effectiveness of any system installed to control or remove suspected hazardous substances; Predict future condition, including but not limited to failure of components; Since this report is provided for the specific benefit of the customer(s), secondary readers of this information should hire a licensed inspector to perform an inspection to meet their specific needs and to obtain current information concerning this property.

Prepared Using HomeGauge http://www.HomeGauge.com : Licensed To Bill Stewart

1000 Glenwick Dr Page 87 of 87